


急傾斜地の崩壊区域調書

様式5-1 危害のおそれのある土地等の座標位置図

調査年度

平成17年度



急傾斜地の崩壊区域調査書

様式5-2 危害のおそれのある土地等の座標一覧

調査年度 平成17年度

急傾斜地の位置	箇所番号	I-0973	箇所名	橋本	所在地	鴨川市大字畑字橋本
---------	------	--------	-----	----	-----	-----------

危害のおそれのある区域の座標(土砂災害警戒区域)					
地点位置	X (m)	Y (m)	地点位置	X (m)	Y (m)
Y-1	17849.46	-100869.14			
Y-2	17860.50	-100840.61			
Y-3	17877.31	-100809.44			
Y-4	17905.70	-100764.28			
Y-5	17956.62	-100824.04			
Y-6	17958.47	-100843.48			
Y-7	17969.37	-100836.46			
Y-8	17980.74	-100846.62			
Y-9	17981.08	-100846.67			
Y-10	17983.26	-100851.79			
Y-11	17985.26	-100855.75			
Y-12	17985.98	-100857.16			
Y-13	17991.85	-100866.64			
Y-14	17993.38	-100870.83			
Y-15	17993.46	-100874.64			
Y-16	17993.57	-100880.49			
Y-17	17993.19	-100887.93			
Y-18	17993.04	-100908.43			
Y-19	17967.52	-100902.66			
Y-20	17964.65	-100902.04			
Y-21	17955.72	-100915.67			
Y-22	17926.35	-100930.71			
Y-23	17911.49	-100932.02			
Y-24	17904.68	-100935.76			
Y-25	17879.68	-100917.76			
Y-26	17878.08	-100910.23			
Y-27	17871.84	-100899.57			
Y-28	17866.48	-100894.37			
Y-29	17858.64	-100886.77			
Y-30	17853.29	-100878.30			
Y-31	17851.44	-100875.37			

著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点位置	X (m)	Y (m)	地点位置	X (m)	Y (m)
R-1	17857.36	-100884.73			
R-2	17867.78	-100856.83			
R-3	17882.09	-100826.48			
R-4	17915.76	-100788.67			
R-5	17949.75	-100840.21			
R-6	17954.71	-100855.72			
R-7	17968.83	-100849.11			
R-8	17982.52	-100861.59			
R-9	17988.41	-100861.10			
R-10	17991.85	-100866.64			
R-11	17993.38	-100870.83			
R-12	17993.46	-100874.64			
R-13	17993.57	-100880.49			
R-14	17993.38	-100884.23			
R-15	17978.16	-100881.58			
R-16	17966.55	-100864.37			
R-17	17954.56	-100869.59			
R-18	17938.91	-100879.67			
R-19	17915.16	-100892.16			
R-20	17902.19	-100893.65			
R-21	17891.42	-100898.21			
R-22	17872.39	-100900.51			
R-23	17871.84	-100899.57			
R-24	17866.48	-100894.37			
R-25	17858.64	-100886.77			

座標値はGISで計測した値を記載