


# 急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度 令和5年度



# 急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和5年度

急傾斜地の位置	箇所番号	II-042K2052		箇所名	青山3	所在地	我孫子市青山、柴崎				
危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-13064.64	19169.16	Y-30	-13085.61	19140.52	R-1	-13047.62	19165.98			
Y-2	-13067.70	19161.86	Y-31	-13085.56	19140.98	R-2	-13051.39	19158.79			
Y-3	-13066.22	19161.58	Y-32	-13085.34	19142.97	R-3	-13046.70	19157.90			
Y-4	-13057.88	19160.01	Y-33	-13084.41	19151.44	R-4	-13042.51	19165.02			
Y-5	-13051.39	19158.79	Y-34	-13084.25	19152.91	R-5	-13041.33	19174.38			
Y-6	-13041.56	19156.94	Y-35	-13094.26	19154.17	R-6	-13045.94	19175.43			
Y-7	-13037.11	19164.01	Y-36	-13106.18	19154.03						
Y-8	-13036.19	19173.21	Y-37	-13126.50	19149.16						
Y-9	-13045.94	19175.43	Y-38	-13127.74	19150.16						
Y-10	-13053.36	19177.12	Y-39	-13135.16	19136.59						
Y-11	-13062.33	19179.16									
Y-12	-13063.11	19179.34	Y-40	-13179.48	19004.34						
			Y-41	-13179.85	18994.68						
Y-13	-13140.28	19123.91	Y-42	-13164.00	18993.40						
Y-14	-13143.49	19113.55	Y-43	-13148.11	19006.29						
Y-15	-13142.28	19113.09	Y-44	-13138.31	19017.66						
Y-16	-13144.30	19106.65	Y-45	-13134.80	19024.06						
Y-17	-13134.80	19103.53	Y-46	-13131.17	19039.09						
Y-18	-13132.90	19102.91	Y-47	-13138.84	19044.45						
Y-19	-13132.70	19102.84	Y-48	-13139.37	19044.82						
Y-20	-13122.45	19099.47	Y-49	-13142.98	19047.35						
Y-21	-13119.37	19106.65	Y-50	-13149.93	19052.21						
Y-22	-13119.34	19106.73	Y-51	-13151.17	19053.08						
Y-23	-13116.57	19115.34	Y-52	-13161.23	19040.05						
Y-24	-13112.65	19125.27	Y-53	-13163.67	19034.05						
Y-25	-13108.80	19134.15	Y-54	-13171.27	19023.24						
Y-26	-13108.79	19134.18	Y-55	-13171.54	19017.55						
Y-27	-13105.88	19129.63	Y-56	-13178.95	19018.36						
Y-28	-13093.73	19129.78	Y-57	-13179.33	19008.37						
Y-29	-13086.66	19131.04	Y-58	-13179.47	19004.67						

平面直角座標系：第IX系(測地成果2011)