


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度	令和4年度
------	-------



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度 令和4年度

急傾斜地の位置	箇所番号	II-061K2490	箇所名	宝田43	所在地	成田市宝田		
危害のおそれのある区域の座標(土砂災害警戒区域)				著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)				
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-20471.82	42642.90	Y-31	-20415.00	42761.80	R-1	-20477.87	42648.13
Y-2	-20488.74	42657.54	Y-32	-20419.27	42760.68	R-2	-20479.97	42636.19
Y-3	-20484.83	42638.99	Y-33	-20431.55	42751.82	R-3	-20476.17	42633.99
Y-4	-20482.43	42637.61				R-4	-20465.34	42639.47
Y-5	-20476.17	42633.99				R-5	-20469.94	42641.27
Y-6	-20471.76	42631.44				R-6	-20471.82	42642.90
Y-7	-20463.10	42626.44				R-7	-20436.75	42737.94
Y-8	-20449.59	42636.78				R-8	-20455.03	42726.88
Y-9	-20453.12	42637.34				R-9	-20451.68	42723.83
Y-10	-20459.47	42638.35				R-10	-20451.52	42723.70
Y-11	-20464.60	42639.18				R-11	-20434.89	42734.87
Y-12	-20469.94	42641.27				R-12	-20424.65	42741.14
Y-13	-20440.36	42743.88				R-13	-20414.18	42748.40
Y-14	-20459.38	42730.82				R-14	-20413.66	42749.49
Y-15	-20451.68	42723.83				R-15	-20413.75	42750.35
Y-16	-20450.75	42723.00				R-16	-20414.31	42755.47
Y-17	-20447.75	42720.28				R-17	-20416.55	42754.12
Y-18	-20440.54	42713.75				R-18	-20427.86	42746.11
Y-19	-20440.40	42713.52						
Y-20	-20427.81	42723.19						
Y-21	-20416.46	42728.47						
Y-22	-20409.17	42734.27						
Y-23	-20409.58	42735.51						
Y-24	-20409.72	42736.32						
Y-25	-20411.46	42742.09						
Y-26	-20412.10	42744.07						
Y-27	-20413.14	42747.31						
Y-28	-20413.25	42747.66						
Y-29	-20413.65	42749.40						
Y-30	-20413.75	42750.35						

平面直角座標系:第IX系(測地成果2011)