

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	令和5年度
------	-------

急傾斜地の位置	箇所番号	II-132K2008	箇所名	横尾1	所在地	鴨川市横尾
---------	------	-------------	-----	-----	-----	-------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-95525.06	15614.96	Y30	-95485.62	15665.42	R1	-95521.50	15611.09			
Y2	-95512.74	15625.92	Y31	-95485.62	15665.45	R2	-95508.85	15622.06			
Y3	-95504.78	15631.81				R3	-95498.82	15631.50			
Y4	-95507.05	15637.14				R4	-95501.74	15637.52			
Y5	-95502.22	15637.49				R5	-95497.08	15637.86			
Y6	-95497.08	15637.86				R6	-95494.20	15631.25			
Y7	-95491.70	15638.24				R7	-95505.16	15618.41			
Y8	-95489.10	15638.01				R8	-95518.29	15607.59			
Y9	-95482.69	15637.45				R9	-95520.18	15609.65			
Y10	-95479.14	15637.13									
Y11	-95479.32	15630.48				R10	-95486.74	15669.95			
Y12	-95493.26	15606.65				R11	-95474.78	15673.48			
Y13	-95506.45	15594.71				R12	-95462.46	15666.25			
Y14	-95510.61	15599.24				R13	-95462.42	15661.56			
Y15	-95513.22	15602.07				R14	-95473.62	15666.42			
Y16	-95518.29	15607.59				R15	-95485.62	15665.42			
Y17	-95520.18	15609.65				R16	-95485.62	15665.45			
Y18	-95488.03	15675.13									
Y19	-95475.90	15680.23									
Y20	-95462.51	15671.56									
Y21	-95462.50	15670.12									
Y22	-95462.42	15661.56									
Y23	-95462.36	15655.56									
Y24	-95462.32	15651.24									
Y25	-95462.27	15645.56									
Y26	-95470.66	15648.47									
Y27	-95481.28	15647.96									
Y28	-95482.98	15654.80									
Y29	-95483.69	15657.66									

平面直角座標系：第Ⅸ系(測地成果2011)