



急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度	令和5年度
------	-------

急傾斜地の位置	箇所番号	II-132K2012	箇所名	横尾5	所在地	鴨川市横尾
---------	------	-------------	-----	-----	-----	-------



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	令和5年度
------	-------

急傾斜地の位置	箇所番号	II-132K2012	箇所名	横尾5	所在地	鴨川市横尾
---------	------	-------------	-----	-----	-----	-------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-94855.10	16345.92	Y30	-94784.46	16312.40	R1	-94854.68	16340.60			
Y2	-94854.25	16365.97	Y31	-94786.76	16313.55	R2	-94847.36	16344.57			
Y3	-94839.51	16370.42	Y32	-94793.41	16316.88	R3	-94836.73	16347.64			
Y4	-94838.09	16358.78	Y33	-94813.33	16326.84	R4	-94835.63	16338.66			
Y5	-94835.63	16338.66	Y34	-94818.11	16330.35	R5	-94833.62	16322.10			
Y6	-94832.70	16314.58	Y35	-94838.80	16345.55	R6	-94839.58	16320.42			
Y7	-94831.74	16306.71				R7	-94854.32	16335.95			
Y8	-94831.49	16304.65									
Y9	-94833.13	16304.02				R8	-94824.96	16335.38			
Y10	-94851.18	16318.36				R9	-94820.88	16347.05			
Y11	-94851.74	16320.04				R10	-94830.01	16352.50			
Y12	-94853.49	16325.28				R11	-94847.60	16370.64			
Y13	-94853.70	16327.97				R12	-94844.54	16385.01			
Y14	-94854.32	16335.95				R13	-94837.35	16380.06			
Y15	-94855.08	16345.60				R14	-94826.43	16372.54			
						R15	-94818.23	16369.88			
Y16	-94838.80	16345.55				R16	-94817.93	16368.75			
Y17	-94841.27	16343.59				R17	-94816.15	16362.52			
Y18	-94873.65	16372.30				R18	-94795.15	16344.11			
Y19	-94866.50	16400.14				R19	-94801.12	16320.73			
Y20	-94852.16	16390.26				R20	-94813.33	16326.84			
Y21	-94837.35	16380.06				R21	-94818.11	16330.35			
Y22	-94826.43	16372.54									
Y23	-94816.30	16369.25									
Y24	-94809.72	16368.87									
Y25	-94803.56	16368.51									
Y26	-94799.73	16368.29									
Y27	-94799.63	16367.59									
Y28	-94799.15	16366.53									
Y29	-94777.29	16344.44									

平面直角座標系: 第Ⅸ系(測地成果2011)