


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度	令和5年度
------	-------

急傾斜地の位置	箇所番号	II-132K2194	箇所名	吉尾西1	所在地	鴨川市吉尾西、西
---------	------	-------------	-----	------	-----	----------



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	令和5年度
------	-------

急傾斜地の位置	箇所番号	II-132K2194	箇所名	吉尾西1	所在地	鴨川市吉尾西、西
---------	------	-------------	-----	------	-----	----------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-99192.51	16178.95	Y31	-99169.68	16171.54	R1	-99177.55	16174.09			
Y2	-99189.04	16203.65	Y32	-99179.43	16174.70	R2	-99161.66	16189.18			
Y3	-99199.21	16205.54				R3	-99164.24	16206.34			
Y4	-99198.45	16208.03				R4	-99164.10	16222.89			
Y5	-99200.52	16234.81				R5	-99167.29	16242.66			
Y6	-99216.55	16262.83				R6	-99177.56	16262.58			
Y7	-99207.88	16299.94				R7	-99171.67	16285.89			
Y8	-99191.09	16329.98				R8	-99160.32	16306.03			
Y9	-99160.02	16305.80				R9	-99160.02	16305.80			
Y10	-99151.63	16299.27				R10	-99151.63	16299.27			
Y11	-99124.61	16278.25				R11	-99129.39	16281.97			
Y12	-99121.00	16275.45				R12	-99134.77	16271.58			
Y13	-99126.19	16264.60				R13	-99138.41	16262.33			
Y14	-99126.73	16262.61				R14	-99136.04	16250.04			
Y15	-99126.98	16260.66				R15	-99135.70	16235.19			
Y16	-99126.86	16258.23				R16	-99128.17	16207.16			
Y17	-99126.13	16253.67				R17	-99130.90	16172.93			
Y18	-99125.83	16250.73				R18	-99160.56	16168.57			
Y19	-99125.74	16247.73				R19	-99169.68	16171.54			
Y20	-99125.95	16241.44									
Y21	-99120.63	16238.27									
Y22	-99110.72	16207.56									
Y23	-99112.68	16184.99									
Y24	-99115.72	16178.51									
Y25	-99120.07	16167.83									
Y26	-99120.54	16166.10									
Y27	-99120.71	16164.07									
Y28	-99144.54	16163.37									
Y29	-99150.34	16165.25									
Y30	-99154.05	16166.46									

平面直角座標系: 第Ⅸ系(測地成果2011)