


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度 令和5年度



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	令和5年度
------	-------

急傾斜地の位置	箇所番号	II-141K2167-1	箇所名	真里谷124	所在地	木更津市真里谷
---------	------	---------------	-----	--------	-----	---------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-70078.10	20851.65				R-1	-70065.54	20853.38			
Y-2	-70076.76	20840.52				R-2	-70065.87	20853.34			
Y-3	-70085.83	20841.98				R-3	-70064.40	20834.56			
Y-4	-70104.36	20837.78				R-4	-70082.60	20827.54			
Y-5	-70103.72	20834.10				R-5	-70101.53	20821.47			
Y-6	-70102.65	20827.92				R-6	-70100.72	20816.78			
Y-7	-70101.53	20821.47				R-7	-70080.90	20819.94			
Y-8	-70100.54	20815.78				R-8	-70058.81	20831.87			
Y-9	-70099.82	20811.62				R-9	-70063.64	20853.65			
Y-10	-70078.98	20811.34									
Y-11	-70050.06	20827.65									
Y-12	-70054.23	20854.94									
Y-13	-70061.37	20853.96									
Y-14	-70065.54	20853.38									
Y-15	-70068.19	20853.02									
Y-16	-70070.91	20852.65									

平面直角座標系：第IX系(測地成果2011)

