


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度 令和5年度



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和5年度

急傾斜地の位置 箇所番号 II-141K2172-1 箇所名 真里谷127 所在地 木更津市真里谷

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-69923.66	23023.41	Y-31	-69879.79	22999.21	R-1	-69930.69	23022.63			
Y-2	-69919.22	23036.62	Y-32	-69889.04	23012.99	R-2	-69929.66	23038.84			
Y-3	-69918.80	23042.97				R-3	-69924.92	23049.50			
Y-4	-69927.25	23052.00				R-4	-69927.25	23052.00			
Y-5	-69929.14	23054.01				R-5	-69929.14	23054.01			
Y-6	-69934.73	23059.99				R-6	-69931.03	23056.03			
Y-7	-69936.45	23061.82				R-7	-69941.19	23041.29			
Y-8	-69941.56	23067.29				R-8	-69938.25	23021.80			
Y-9	-69956.97	23044.65				R-9	-69962.28	22988.93			
Y-10	-69954.75	23019.99				R-10	-69961.94	22980.36			
Y-11	-69973.80	22989.44				R-11	-69961.64	22978.69			
Y-12	-69974.37	22990.61				R-12	-69961.71	22978.27			
Y-13	-69975.42	22990.68				R-13	-69963.90	22977.62			
Y-14	-69975.92	22989.52				R-14	-69967.25	22976.13			
Y-15	-69977.07	22988.71				R-15	-69981.68	22976.12			
Y-16	-69977.96	22987.46				R-16	-69982.99	22973.06			
Y-17	-69977.96	22987.46				R-17	-69984.67	22967.45			
Y-18	-69978.43	22986.33				R-18	-69986.60	22948.61			
Y-19	-69978.25	22984.09				R-19	-69987.29	22941.89			
Y-20	-69978.80	22982.81				R-20	-69987.74	22937.58			
Y-21	-69979.37	22981.49				R-21	-69965.73	22935.14			
Y-22	-69982.99	22973.06				R-22	-69940.51	22938.70			
Y-23	-69984.67	22967.45				R-23	-69921.55	22945.47			
Y-24	-69986.60	22948.61				R-24	-69913.94	22963.15			
Y-25	-69987.29	22941.89				R-25	-69916.99	22985.62			
Y-26	-69991.70	22898.87				R-26	-69926.85	23003.16			
Y-27	-69966.25	22896.23									
Y-28	-69926.99	22901.74									
Y-29	-69890.92	22919.09									
Y-30	-69875.24	22951.76									

平面直角座標系：第IX系(測地成果2011)

