


急傾斜地の崩壊区域調書

様式5-1 危害のおそれのある土地等の座標位置図(1/2)

調査年度

平成19年度



急傾斜地の崩壊区域調書

様式5-2 危害のおそれのある土地等の座標一覧(1/2)

調査年度	平成19年度
------	--------

急傾斜地の位置	箇所番号	I-0621	箇所名	下森戸	所在地	千葉県銚子市森戸町					
危害のおそれのある土地の区域の座標(土砂災害警戒区域)											
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	80894.57	-23846.71	Y-36	80868.39	-23736.20						
Y-2	80895.46	-23830.67	Y-37	80870.46	-23742.00						
Y-3	80900.49	-23810.67	Y-38	80866.79	-23751.03						
Y-4	80894.49	-23795.48	Y-39	80856.46	-23763.42						
Y-5	80893.72	-23779.77	Y-40	80846.48	-23777.35						
Y-6	80895.29	-23773.61	Y-41	80858.42	-23801.53						
Y-7	80894.46	-23766.39	Y-42	80866.43	-23812.89						
Y-8	80916.20	-23746.03	Y-43	80869.61	-23834.47						
Y-9	80950.74	-23704.96	Y-44	80872.45	-23850.02						
Y-10	80946.65	-23695.16	Y-45	80882.34	-23848.54						
Y-11	80945.58	-23685.12	Y-46	80884.68	-23848.19						
Y-12	80915.40	-23661.37									
Y-13	80888.98	-23639.75									
Y-14	80875.15	-23629.72									
Y-15	80865.56	-23618.67									
Y-16	80861.05	-23598.83									
Y-17	80848.53	-23583.40									
Y-18	80847.21	-23580.66									
Y-19	80849.66	-23566.89									
Y-20	80808.91	-23590.43									
Y-21	80803.67	-23593.46									
Y-22	80795.33	-23598.20									
Y-23	80792.34	23600.25									
Y-24	80783.19	-23606.98									
Y-25	80778.07	-23610.74									
Y-26	80775.13	-23612.90									
Y-27	80787.77	-23624.74									
Y-28	80803.08	-23637.92									
Y-29	80807.92	-23641.27									
Y-30	80814.11	-23654.92									
Y-31	80829.07	-23681.61									
Y-32	80846.11	-23694.23									
Y-33	80854.15	-23700.81									
Y-34	80857.87	-23705.26									
Y-35	80863.33	-23723.05									

急傾斜地の崩壊区域調書

様式5-2 危害のおそれのある土地等の座標一覧(2/2)

調査年度	平成19年度
------	--------

急傾斜地の位置	箇所番号	I-0621	箇所名	下森戸	所在地	千葉県銚子市森戸町					
著しい危害のおそれのある土地の区域の座標(土砂災害特別警戒区域)											
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
R-1	80886.34	-23847.94	R-36	80877.12	-23756.77						
R-2	80883.52	-23832.42	R-37	80869.14	-23766.75						
R-3	80891.69	-23811.17	R-38	80863.08	-23778.20						
R-4	80884.55	-23797.15	R-39	80873.99	-23798.92						
R-5	80879.33	-23779.03	R-40	80882.30	-23811.73						
R-6	80878.22	-23769.13	R-41	80881.38	-23832.74						
R-7	80880.09	-23758.41	R-42	80884.68	-23848.19						
R-8	80902.64	-23745.26									
R-9	80914.68	-23720.36									
R-10	80909.30	-23707.03									
R-11	80907.35	-23693.04									
R-12	80891.81	-23674.91									
R-13	80874.39	-23658.15									
R-14	80859.86	-23648.01									
R-15	80848.80	-23632.25									
R-16	80839.58	-23616.18									
R-17	80829.02	-23604.79									
R-18	80821.38	-23597.74									
R-19	80818.01	-23585.17									
R-20	80808.91	-23590.43									
R-21	80803.67	-23593.46									
R-22	80795.33	-23598.20									
R-23	80792.34	-23600.25									
R-24	80788.43	-23603.13									
R-25	80799.03	-23613.95									
R-26	80812.09	-23625.09									
R-27	80819.76	-23631.27									
R-28	80829.42	-23646.67									
R-29	80841.73	-23668.50									
R-30	80857.40	-23679.55									
R-31	80867.43	-23690.05									
R-32	80872.68	-23701.09									
R-33	80877.64	-23717.78									
R-34	80883.34	-23732.13									
R-35	80887.11	-23744.14									