


# 急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度 令和5年度



# 急傾斜地の崩壊区域調査

様式5-5 危害のおそれのある土地の座標一覧

調査年度	令和5年度
------	-------

急傾斜地の位置	箇所番号	I-041K2087	箇所名	東山3	所在地	柏市東山2丁目
---------	------	------------	-----	-----	-----	---------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-19231.72	10762.44	Y-30	-19214.46	10777.10	R-1	-19283.93	10857.74			
Y-2	-19238.49	10764.50	Y-31	-19212.14	10787.93	R-2	-19291.63	10845.36			
Y-3	-19243.65	10766.08	Y-32	-19209.78	10799.02	R-3	-19293.39	10824.78			
Y-4	-19249.42	10767.84	Y-33	-19212.11	10808.97	R-4	-19293.12	10814.48			
Y-5	-19253.22	10768.99	Y-34	-19212.12	10809.01	R-5	-19287.39	10814.54			
Y-6	-19261.41	10752.78	Y-35	-19214.84	10816.00	R-6	-19280.69	10814.62			
Y-7	-19259.68	10739.36	Y-36	-19218.24	10814.85	R-7	-19286.34	10825.99			
Y-8	-19262.48	10722.45	Y-37	-19224.32	10812.80	R-8	-19282.26	10843.29			
Y-9	-19258.45	10714.08	Y-38	-19224.33	10812.80	R-9	-19279.67	10855.81			
Y-10	-19254.10	10714.46									
Y-11	-19248.49	10714.95	Y-39	-19279.59	10827.15						
Y-12	-19242.90	10715.44	Y-40	-19273.99	10841.47						
Y-13	-19236.34	10716.01	Y-41	-19274.82	10853.61						
Y-14	-19232.94	10716.31	Y-42	-19277.77	10854.95						
Y-15	-19230.71	10723.88	Y-43	-19283.93	10857.74						
Y-16	-19232.28	10738.99	Y-44	-19291.21	10861.05						
Y-17	-19231.87	10747.53	Y-45	-19297.61	10863.95						
Y-18	-19228.92	10761.59	Y-46	-19300.32	10865.18						
			Y-47	-19309.54	10849.30						
Y-19	-19226.05	10812.22	Y-48	-19311.33	10821.71						
Y-20	-19234.56	10809.35	Y-49	-19311.11	10814.28						
Y-21	-19231.72	10800.92	Y-50	-19301.12	10814.39						
Y-22	-19230.97	10801.19	Y-51	-19287.39	10814.54						
Y-23	-19229.88	10801.64	Y-52	-19280.30	10814.62						
Y-24	-19231.95	10792.86									
Y-25	-19234.61	10781.43									
Y-26	-19225.82	10779.55									
Y-27	-19224.24	10779.21									
Y-28	-19224.24	10779.21									
Y-29	-19218.00	10777.86									

平面直角座標系：第IX系(測地成果2011)