


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

| | |
|------|--------|
| 調査年度 | 平成28年度 |
|------|--------|

| | | | | | | |
|---------|------|---------|-----|-------|-----|-----------|
| 急傾斜地の位置 | 箇所番号 | II-1573 | 箇所名 | 不動ヶ岡1 | 所在地 | 成田市不動ヶ岡太田 |
|---------|------|---------|-----|-------|-----|-----------|



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度

平成28年度

| 急傾斜地の位置 | | 箇所番号 | II-1573 | | 箇所名 | 不動ヶ岡1 | | 所在地 | 成田市不動ヶ岡太田 | | |
|--------------------------|-----------|----------|---------|-----------|----------|-------------------------------|-----------|----------|-----------|------|------|
| 危害のおそれのある区域の座標(土砂災害警戒区域) | | | | | | 著しい危害のおそれのある区域の座標(土砂災害特別警戒区域) | | | | | |
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
| Y-1 | -25482.29 | 43632.40 | Y-31 | -25415.46 | 43645.80 | R-1 | -25475.83 | 43625.42 | | | |
| Y-2 | -25467.84 | 43637.23 | Y-32 | -25421.72 | 43647.28 | R-2 | -25465.05 | 43631.90 | | | |
| Y-3 | -25451.04 | 43640.82 | | | | R-3 | -25448.43 | 43630.66 | | | |
| Y-4 | -25435.33 | 43645.29 | | | | R-4 | -25434.68 | 43632.25 | | | |
| Y-5 | -25429.26 | 43626.01 | | | | R-5 | -25429.93 | 43620.25 | | | |
| Y-6 | -25430.45 | 43615.82 | | | | R-6 | -25430.45 | 43615.82 | | | |
| Y-7 | -25431.04 | 43610.66 | | | | R-7 | -25430.46 | 43615.69 | | | |
| Y-8 | -25431.98 | 43602.60 | | | | R-8 | -25433.96 | 43617.58 | | | |
| Y-9 | -25432.20 | 43600.72 | | | | R-9 | -25445.58 | 43619.61 | | | |
| Y-10 | -25433.14 | 43601.15 | | | | R-10 | -25462.26 | 43626.59 | | | |
| Y-11 | -25441.59 | 43604.12 | | | | R-11 | -25468.83 | 43617.85 | | | |
| Y-12 | -25454.61 | 43612.01 | | | | R-12 | -25471.33 | 43620.55 | | | |
| Y-13 | -25457.97 | 43606.10 | | | | R-13 | -25424.66 | 43654.16 | | | |
| Y-14 | -25463.27 | 43611.84 | | | | R-14 | -25424.66 | 43654.38 | | | |
| Y-15 | -25464.76 | 43613.45 | | | | R-15 | -25432.62 | 43660.36 | | | |
| Y-16 | -25471.33 | 43620.55 | | | | R-16 | -25427.95 | 43676.24 | | | |
| Y-17 | -25431.96 | 43649.70 | | | | R-17 | -25422.30 | 43672.00 | | | |
| Y-18 | -25433.14 | 43656.97 | | | | R-18 | -25418.54 | 43669.17 | | | |
| Y-19 | -25433.14 | 43657.19 | | | | R-19 | -25421.73 | 43658.90 | | | |
| Y-20 | -25441.93 | 43661.61 | | | | R-20 | -25414.87 | 43651.14 | | | |
| Y-21 | -25436.76 | 43682.85 | | | | R-21 | -25414.88 | 43650.92 | | | |
| Y-22 | -25422.30 | 43672.00 | | | | R-22 | -25418.52 | 43652.12 | | | |
| Y-23 | -25413.89 | 43665.68 | | | | | | | | | |
| Y-24 | -25412.21 | 43664.42 | | | | | | | | | |
| Y-25 | -25405.89 | 43659.67 | | | | | | | | | |
| Y-26 | -25403.93 | 43656.51 | | | | | | | | | |
| Y-27 | -25398.62 | 43645.77 | | | | | | | | | |
| Y-28 | -25398.63 | 43645.54 | | | | | | | | | |
| Y-29 | -25405.73 | 43643.50 | | | | | | | | | |
| Y-30 | -25412.58 | 43645.12 | | | | | | | | | |