


急傾斜地の崩壊区域調書

様式5-1 危害のおそれのある土地等の座標位置図(1/2)

調査年度

平成18年度



急傾斜地の崩壊区域調書

様式5-2 危害のおそれのある土地等の座標一覧(1/2)

調査年度	平成18年度
------	--------

急傾斜地の位置	箇所番号	Ⅱ-5046	箇所名	東長田9	所在地	千葉県館山市東長田
---------	------	--------	-----	------	-----	-----------

危害のおそれのある土地の区域の座標(土砂災害警戒区域)

地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-a1	4316.92	-114660.27	Y-b9	4317.56	-114805.93						
Y-a2	4317.77	-114662.34	Y-b10	4325.94	-114779.29						
Y-a3	4309.38	-114664.38	Y-b11	4323.19	-114779.11						
Y-a4	4296.62	-114678.17	Y-b12	4315.96	-114778.64						
Y-a5	4277.40	-114695.33	Y-b13	4311.64	-114778.37						
Y-a6	4271.88	-114712.55	Y-b14	4310.77	-114778.49						
Y-a7	4271.51	-114728.24									
Y-a8	4271.75	-114746.06									
Y-a9	4277.97	-114748.78									
Y-a10	4280.91	-114750.07									
Y-a11	4282.59	-114750.81									
Y-a12	4282.71	-114750.82									
Y-a13	4286.65	-114751.29									
Y-a14	4289.28	-114750.57									
Y-a15	4292.47	-114749.70									
Y-a16	4305.18	-114741.73									
Y-a17	4319.53	-114734.56									
Y-a18	4330.20	-114710.00									
Y-a19	4335.24	-114698.34									
Y-a20	4342.60	-114689.74									
Y-a21	4353.48	-114671.09									
Y-a22	4355.21	-114658.09									
Y-a23	4350.27	-114657.81									
Y-a24	4345.23	-114657.53									
Y-a25	4340.61	-114657.27									
Y-a26	4332.07	-114658.35									
Y-a27	4322.92	-114659.51									
Y-b1	4300.91	-114779.93									
Y-b2	4300.87	-114779.94									
Y-b3	4289.80	-114778.09									
Y-b4	4284.88	-114791.73									
Y-b5	4288.82	-114800.92									
Y-b6	4290.93	-114805.84									
Y-b7	4291.96	-114807.03									
Y-b8	4298.49	-114814.60									

