


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度 令和5年度



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和5年度

急傾斜地の位置 箇所番号 I-041K2037 箇所名 篠籠田1 所在地 柏市篠籠田

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-14381.10	11095.52	Y-30	-14383.34	11001.19	R-1	-14376.90	10988.14			
Y-2	-14384.02	11079.28				R-2	-14386.86	10988.48			
Y-3	-14368.28	11065.98				R-3	-14385.77	10983.91			
Y-4	-14361.62	11060.44				R-4	-14374.83	10983.94			
Y-5	-14356.83	11061.50									
Y-6	-14354.42	11065.27									
Y-7	-14351.44	11069.92									
Y-8	-14349.12	11073.54									
Y-9	-14348.01	11075.28									
Y-10	-14343.73	11081.96									
Y-11	-14342.47	11089.13									
Y-12	-14351.00	11095.95									
Y-13	-14352.77	11095.26									
Y-14	-14358.95	11098.10									
Y-15	-14367.87	11097.06									
Y-16	-14368.88	11096.94									
Y-17	-14371.16	11096.68									
Y-18	-14375.94	11096.12									
Y-19	-14383.98	11002.49									
Y-20	-14390.59	11004.04									
Y-21	-14389.92	11001.28									
Y-22	-14388.26	10994.31									
Y-23	-14386.86	10988.48									
Y-24	-14385.72	10983.71									
Y-25	-14384.54	10978.75									
Y-26	-14372.48	10979.17									
Y-27	-14373.71	10981.67									
Y-28	-14376.90	10988.14									
Y-29	-14379.56	10993.52									

平面直角座標系：第IX系(測地成果2011)