


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度 平成28年度

| | | | | | | |
|---------|------|--------|-----|------|-----|--------------------|
| 急傾斜地の位置 | 箇所番号 | I-0127 | 箇所名 | 宮久保1 | 所在地 | 千葉県市川市宮久保2丁目、曾谷3丁目 |
|---------|------|--------|-----|------|-----|--------------------|



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 平成28年度

| | | | | | | |
|---------|------|--------|-----|------|-----|--------------------|
| 急傾斜地の位置 | 箇所番号 | I-0127 | 箇所名 | 宮久保1 | 所在地 | 千葉県市川市宮久保2丁目、曾谷3丁目 |
|---------|------|--------|-----|------|-----|--------------------|

| 危害のおそれのある区域の座標(土砂災害警戒区域) | | | | | | 著しい危害のおそれのある区域の座標(土砂災害特別警戒区域) | | | | | |
|--------------------------|-----------|---------|------|-----------|---------|-------------------------------|-----------|---------|------|------|------|
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
| Y-1 | -28829.15 | 8879.46 | Y-32 | -28883.51 | 8904.06 | R-1 | -28859.77 | 8866.87 | | | |
| Y-2 | -28824.01 | 8869.16 | Y-33 | -28877.86 | 8895.01 | R-2 | -28874.11 | 8862.77 | | | |
| Y-3 | -28837.83 | 8861.85 | Y-34 | -28875.11 | 8891.86 | R-3 | -28882.68 | 8865.07 | | | |
| Y-4 | -28853.04 | 8853.26 | Y-35 | -28872.83 | 8893.46 | R-4 | -28891.02 | 8870.33 | | | |
| Y-5 | -28853.08 | 8853.24 | Y-36 | -28872.69 | 8893.53 | R-5 | -28891.06 | 8870.40 | | | |
| Y-6 | -28873.59 | 8850.43 | Y-37 | -28858.04 | 8901.84 | R-6 | -28896.68 | 8880.55 | | | |
| Y-7 | -28886.52 | 8851.91 | Y-38 | -28844.00 | 8909.25 | R-7 | -28902.69 | 8890.06 | | | |
| Y-8 | -28900.08 | 8860.12 | Y-39 | -28819.31 | 8919.29 | R-8 | -28904.44 | 8891.67 | | | |
| Y-9 | -28900.12 | 8860.18 | Y-40 | -28805.49 | 8902.48 | R-9 | -28904.56 | 8891.66 | | | |
| Y-10 | -28907.76 | 8872.05 | Y-41 | -28809.40 | 8898.30 | R-10 | -28917.77 | 8886.53 | | | |
| Y-11 | -28912.12 | 8878.92 | Y-42 | -28807.44 | 8893.64 | R-11 | -28924.76 | 8888.17 | | | |
| Y-12 | -28917.83 | 8878.14 | Y-43 | -28813.01 | 8890.00 | R-12 | -28924.82 | 8888.19 | | | |
| Y-13 | -28928.67 | 8880.76 | Y-44 | -28815.81 | 8888.17 | R-13 | -28931.51 | 8896.91 | | | |
| Y-14 | -28928.74 | 8880.79 | Y-45 | -28821.00 | 8884.78 | R-14 | -28929.18 | 8898.62 | | | |
| Y-15 | -28935.02 | 8887.79 | Y-46 | -28823.24 | 8883.32 | R-15 | -28926.79 | 8900.39 | | | |
| Y-16 | -28941.41 | 8885.76 | | | | R-16 | -28924.92 | 8901.78 | | | |
| Y-17 | -28944.15 | 8888.59 | | | | R-17 | -28920.59 | 8896.17 | | | |
| Y-18 | -28942.68 | 8892.02 | | | | R-18 | -28920.54 | 8896.15 | | | |
| Y-19 | -28943.54 | 8894.25 | | | | R-19 | -28917.71 | 8895.52 | | | |
| Y-20 | -28944.20 | 8895.97 | | | | R-20 | -28903.09 | 8905.09 | | | |
| Y-21 | -28945.02 | 8898.11 | | | | R-21 | -28902.99 | 8905.10 | | | |
| Y-22 | -28945.80 | 8900.15 | | | | R-22 | -28894.70 | 8895.89 | | | |
| Y-23 | -28948.61 | 8907.44 | | | | R-23 | -28888.84 | 8886.58 | | | |
| Y-24 | -28937.32 | 8909.55 | | | | R-24 | -28883.24 | 8879.22 | | | |
| Y-25 | -28937.68 | 8910.27 | | | | R-25 | -28883.20 | 8879.14 | | | |
| Y-26 | -28938.10 | 8911.30 | | | | R-26 | -28879.12 | 8877.24 | | | |
| Y-27 | -28932.64 | 8913.80 | | | | R-27 | -28874.67 | 8875.90 | | | |
| Y-28 | -28917.60 | 8911.47 | | | | R-28 | -28866.16 | 8879.88 | | | |
| Y-29 | -28917.60 | 8911.54 | | | | R-29 | -28863.22 | 8873.89 | | | |
| Y-30 | -28901.30 | 8921.43 | | | | R-30 | -28861.73 | 8870.86 | | | |
| Y-31 | -28901.22 | 8921.45 | | | | | | | | | |