


# 急傾斜地の崩壊区域調書

様式5-1 危害のおそれのある土地等の座標位置図(1/2)

調査年度

平成18年度




# 急傾斜地の崩壊区域調書

様式5-1 危害のおそれのある土地等の座標位置図(2/2)

調査年度

平成18年度



## 急傾斜地の崩壊区域調書

様式5-2 危害のおそれのある土地等の座標一覧(1/2)

調査年度	平成18年度
------	--------

急傾斜地の位置	箇所番号	I-0474	箇所名	林1	所在地	香取郡多古町林
---------	------	--------	-----	----	-----	---------

危害のおそれのある区域の座標(土砂災害警戒区域)						危害のおそれのある区域の座標(土砂災害警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	55617.61	-29650.12	Y-32	55814.15	-29520.77						
Y-2	55616.96	-29642.09	Y-33	55814.74	-29521.69						
Y-3	55616.55	-29636.91	Y-34	55815.40	-29522.88						
Y-4	55616.33	-29634.67	Y-35	55815.67	-29523.60						
Y-5	55615.97	-29632.17	Y-36	55818.89	-29534.68						
Y-6	55615.33	-29627.99	Y-37	55813.45	-29538.54						
Y-7	55613.41	-29616.99	Y-38	55808.08	-29545.39						
Y-8	55622.71	-29615.27	Y-39	55800.75	-29547.29						
Y-9	55626.42	-29613.20	Y-40	55782.21	-29556.14						
Y-10	55639.60	-29607.62	Y-41	55775.01	-29550.56						
Y-11	55653.17	-29589.18	Y-42	55768.91	-29547.25						
Y-12	55657.64	-29587.33	Y-43	55761.43	-29537.43						
Y-13	55664.74	-29583.89	Y-44	55755.05	-29534.56						
Y-14	55691.07	-29585.25	Y-45	55744.58	-29552.05						
Y-15	55692.49	-29576.61	Y-46	55743.03	-29555.20						
Y-16	55704.36	-29570.37	Y-47	55741.62	-29557.37						
Y-17	55707.91	-29568.87	Y-48	55736.04	-29566.84						
Y-18	55706.81	-29564.01	Y-49	55758.02	-29591.47						
Y-19	55706.88	-29554.42	Y-50	55739.60	-29616.20						
Y-20	55712.71	-29527.72	Y-51	55723.79	-29625.37						
Y-21	55712.59	-29518.88	Y-52	55706.74	-29624.05						
Y-22	55730.03	-29504.71	Y-53	55699.65	-29619.47						
Y-23	55760.19	-29499.73	Y-54	55692.68	-29625.28						
Y-24	55785.99	-29513.76	Y-55	55676.97	-29613.90						
Y-25	55785.39	-29517.33	Y-56	55675.09	-29621.86						
Y-26	55790.95	-29512.49	Y-57	55681.38	-29640.53						
Y-27	55799.95	-29511.46	Y-58	55654.34	-29636.23						
Y-28	55804.75	-29516.50	Y-59	55635.03	-29638.87						
Y-29	55810.59	-29518.33	Y-60	55630.46	-29649.84						
Y-30	55812.04	-29518.99									
Y-31	55813.17	-29519.72									

## 急傾斜地の崩壊区域調書

様式5-2 危害のおそれのある土地等の座標一覧(2/2)

調査年度	平成18年度
------	--------

急傾斜地の位置	箇所番号	I-0474	箇所名	林1	所在地	香取郡多古町林
---------	------	--------	-----	----	-----	---------

著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
R-1	55670.12	-29624.23	R-32	55688.91	-29614.21						
R-2	55662.98	-29613.86	R-33	55674.17	-29604.58						
R-3	55658.52	-29605.39	R-34	55669.39	-29610.80						
R-4	55664.27	-29600.60	R-35	55811.74	-29531.34						
R-5	55671.52	-29596.77	R-36	55810.27	-29525.12						
R-6	55686.51	-29600.93	R-37	55810.07	-29524.19						
R-7	55691.86	-29601.41	R-38	55809.95	-29523.81						
R-8	55696.74	-29602.35	R-39	55815.71	-29523.73						
R-9	55702.87	-29590.39	R-40	55815.87	-29524.30						
R-10	55714.80	-29584.37	R-41	55817.28	-29529.15						
R-11	55723.33	-29579.22									
R-12	55721.31	-29566.23									
R-13	55724.98	-29556.64									
R-14	55722.47	-29542.43									
R-15	55726.13	-29529.38									
R-16	55739.93	-29518.90									
R-17	55756.28	-29517.25									
R-18	55776.23	-29526.28									
R-19	55774.75	-29530.66									
R-20	55772.42	-29537.26									
R-21	55758.29	-29528.24									
R-22	55748.05	-29527.41									
R-23	55736.76	-29540.92									
R-24	55733.67	-29549.32									
R-25	55733.74	-29557.08									
R-26	55728.03	-29566.54									
R-27	55742.53	-29584.76									
R-28	55728.08	-29601.36									
R-29	55714.16	-29608.86									
R-30	55701.52	-29612.58									
R-31	55695.36	-29610.88									