


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度 令和5年度

急傾斜地の位置 箇所番号 II-123K2127-1 箇所名 久我原5 所在地 夷隅郡大多喜町久我原、三又



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度 令和5年度

| | | | | | | |
|---------|------|---------------|-----|------|-----|---------------|
| 急傾斜地の位置 | 箇所番号 | II-123K2127-1 | 箇所名 | 久我原5 | 所在地 | 夷隅郡大多喜町久我原、三叉 |
|---------|------|---------------|-----|------|-----|---------------|

危害のおそれのある土地の座標

| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
|------|------------|-----------|------|------------|-----------|
| Y-1 | -82,904.48 | 37,401.53 | Y-28 | -83,094.51 | 37,443.36 |
| Y-2 | -82,912.03 | 37,378.88 | Y-29 | -83,072.11 | 37,433.52 |
| Y-3 | -82,955.09 | 37,347.70 | Y-30 | -83,068.55 | 37,432.47 |
| Y-4 | -82,976.09 | 37,340.22 | Y-31 | -83,066.46 | 37,431.63 |
| Y-5 | -82,992.45 | 37,335.71 | Y-32 | -83,050.94 | 37,426.76 |
| Y-6 | -83,005.85 | 37,331.04 | Y-33 | -83,044.18 | 37,422.95 |
| Y-7 | -83,037.32 | 37,324.90 | Y-34 | -83,038.88 | 37,421.58 |
| Y-8 | -83,049.21 | 37,325.71 | Y-35 | -83,034.99 | 37,421.21 |
| Y-9 | -83,056.87 | 37,327.46 | Y-36 | -83,031.64 | 37,421.55 |
| Y-10 | -83,094.94 | 37,353.71 | Y-37 | -83,031.09 | 37,421.39 |
| Y-11 | -83,088.92 | 37,358.81 | Y-38 | -83,028.95 | 37,421.44 |
| Y-12 | -83,084.15 | 37,367.42 | Y-39 | -83,028.23 | 37,421.47 |
| Y-13 | -83,092.85 | 37,362.65 | Y-40 | -83,026.97 | 37,421.95 |
| Y-14 | -83,107.60 | 37,356.90 | Y-41 | -83,026.83 | 37,422.04 |
| Y-15 | -83,144.00 | 37,362.71 | Y-42 | -83,025.26 | 37,422.20 |
| Y-16 | -83,133.81 | 37,387.40 | Y-43 | -83,019.83 | 37,422.48 |
| Y-17 | -83,125.11 | 37,408.46 | Y-44 | -83,015.96 | 37,422.85 |
| Y-18 | -83,121.19 | 37,417.96 | Y-45 | -83,006.30 | 37,425.27 |
| Y-19 | -83,116.11 | 37,429.15 | Y-46 | -83,000.24 | 37,428.19 |
| Y-20 | -83,112.51 | 37,437.47 | Y-47 | -82,998.56 | 37,428.33 |
| Y-21 | -83,112.29 | 37,437.96 | Y-48 | -82,997.16 | 37,428.56 |
| Y-22 | -83,109.83 | 37,443.54 | Y-49 | -82,997.08 | 37,428.46 |
| Y-23 | -83,109.73 | 37,443.76 | Y-50 | -82,996.91 | 37,428.58 |
| Y-24 | -83,107.85 | 37,443.64 | Y-51 | -82,992.11 | 37,424.07 |
| Y-25 | -83,105.01 | 37,444.29 | Y-52 | -82,989.63 | 37,421.73 |
| Y-26 | -83,099.10 | 37,444.85 | Y-53 | -82,986.71 | 37,418.99 |
| Y-27 | -83,097.27 | 37,444.55 | Y-54 | -82,981.95 | 37,414.96 |

著しい危害のおそれのある土地の座標

| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
|------|------------|-----------|------|------------|-----------|
| R-1 | -82,943.17 | 37,405.34 | R-28 | -82,984.83 | 37,416.61 |
| R-2 | -82,947.44 | 37,396.13 | R-29 | -82,984.91 | 37,417.46 |
| R-3 | -82,969.62 | 37,383.96 | R-30 | -82,981.95 | 37,414.96 |
| R-4 | -82,986.97 | 37,377.77 | R-31 | -82,977.50 | 37,412.00 |
| R-5 | -83,003.86 | 37,373.01 | R-32 | -82,973.27 | 37,409.99 |
| R-6 | -83,019.05 | 37,367.89 | R-33 | -82,968.40 | 37,408.51 |
| R-7 | -83,044.11 | 37,361.96 | R-34 | -82,962.37 | 37,407.24 |
| R-8 | -83,062.20 | 37,376.31 | R-35 | -82,954.23 | 37,406.44 |
| R-9 | -83,062.47 | 37,388.03 | | | |
| R-10 | -83,074.26 | 37,396.66 | | | |
| R-11 | -83,090.95 | 37,397.01 | | | |
| R-12 | -83,106.66 | 37,395.89 | | | |
| R-13 | -83,129.18 | 37,398.60 | | | |
| R-14 | -83,125.11 | 37,408.46 | | | |
| R-15 | -83,121.19 | 37,417.96 | | | |
| R-16 | -83,116.11 | 37,429.15 | | | |
| R-17 | -83,115.04 | 37,431.60 | | | |
| R-18 | -83,106.34 | 37,433.67 | | | |
| R-19 | -83,089.47 | 37,429.28 | | | |
| R-20 | -83,066.38 | 37,421.85 | | | |
| R-21 | -83,041.72 | 37,411.35 | | | |
| R-22 | -83,035.21 | 37,406.31 | | | |
| R-23 | -83,033.68 | 37,405.95 | | | |
| R-24 | -83,031.15 | 37,407.26 | | | |
| R-25 | -83,015.72 | 37,411.01 | | | |
| R-26 | -82,995.07 | 37,412.92 | | | |
| R-27 | -82,987.03 | 37,416.28 | | | |

平面直角座標系：第Ⅸ区系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

| | |
|------|-------|
| 調査年度 | 令和5年度 |
|------|-------|

| | | | | | | |
|---------|------|---------------|-----|------|-----|---------------|
| 急傾斜地の位置 | 箇所番号 | II-123K2127-1 | 箇所名 | 久我原5 | 所在地 | 夷隅郡大多喜町久我原、三又 |
|---------|------|---------------|-----|------|-----|---------------|

| 危害のおそれのある土地の座標 | | | | | | 著しい危害のおそれのある土地の座標 | | | | | |
|----------------|------------|-----------|------|------|------|-------------------|------|------|------|------|------|
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
| Y-55 | -82,977.50 | 37,412.00 | | | | | | | | | |
| Y-56 | -82,973.27 | 37,409.99 | | | | | | | | | |
| Y-57 | -82,968.40 | 37,408.51 | | | | | | | | | |
| Y-58 | -82,962.37 | 37,407.24 | | | | | | | | | |
| Y-59 | -82,954.23 | 37,406.44 | | | | | | | | | |
| Y-60 | -82,906.59 | 37,401.73 | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |


平面直角座標系: 第IX系(測地成果2011)

急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度 令和5年度

急傾斜地の位置 箇所番号 II-123K2127-2 箇所名 久我原5 所在地 夷隅郡大多喜町久我原、三又



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度 令和5年度

| | | | | | | |
|---------|------|---------------|-----|------|-----|---------------|
| 急傾斜地の位置 | 箇所番号 | II-123K2127-2 | 箇所名 | 久我原5 | 所在地 | 夷隅郡大多喜町久我原、三又 |
|---------|------|---------------|-----|------|-----|---------------|

| 危害のおそれのある土地の座標 | | | | | |
|----------------|------------|-----------|------|------|------|
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
| Y-1 | -83,091.76 | 37,407.42 | | | |
| Y-2 | -83,091.13 | 37,382.50 | | | |
| Y-3 | -83,101.04 | 37,359.93 | | | |
| Y-4 | -83,129.58 | 37,339.79 | | | |
| Y-5 | -83,133.10 | 37,355.41 | | | |
| Y-6 | -83,138.92 | 37,381.21 | | | |
| Y-7 | -83,140.47 | 37,388.11 | | | |
| Y-8 | -83,143.09 | 37,394.70 | | | |
| Y-9 | -83,145.62 | 37,398.91 | | | |
| Y-10 | -83,149.45 | 37,404.07 | | | |
| Y-11 | -83,151.97 | 37,406.53 | | | |
| Y-12 | -83,153.88 | 37,407.79 | | | |
| Y-13 | -83,154.01 | 37,407.84 | | | |
| Y-14 | -83,156.20 | 37,408.74 | | | |
| Y-15 | -83,162.00 | 37,410.85 | | | |
| Y-16 | -83,163.37 | 37,411.35 | | | |
| Y-17 | -83,163.30 | 37,411.49 | | | |
| Y-18 | -83,163.27 | 37,411.58 | | | |
| Y-19 | -83,163.32 | 37,411.66 | | | |
| Y-20 | -83,159.04 | 37,410.28 | | | |
| Y-21 | -83,157.34 | 37,409.73 | | | |
| Y-22 | -83,153.66 | 37,409.29 | | | |
| Y-23 | -83,153.65 | 37,409.29 | | | |
| Y-24 | -83,145.09 | 37,408.39 | | | |
| Y-25 | -83,136.75 | 37,408.07 | | | |
| Y-26 | -83,127.53 | 37,407.94 | | | |
| Y-27 | -83,095.60 | 37,407.48 | | | |

| 著しい危害のおそれのある土地の座標 | | | | | |
|-------------------|------------|-----------|------|------|------|
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
| R-1 | -83,118.03 | 37,407.80 | | | |
| R-2 | -83,119.75 | 37,393.88 | | | |
| R-3 | -83,125.14 | 37,380.61 | | | |
| R-4 | -83,136.74 | 37,371.54 | | | |
| R-5 | -83,138.92 | 37,381.21 | | | |
| R-6 | -83,140.47 | 37,388.11 | | | |
| R-7 | -83,143.09 | 37,394.70 | | | |
| R-8 | -83,145.62 | 37,398.91 | | | |
| R-9 | -83,148.58 | 37,402.90 | | | |
| R-10 | -83,148.09 | 37,403.89 | | | |
| R-11 | -83,147.82 | 37,405.64 | | | |
| R-12 | -83,146.38 | 37,408.53 | | | |
| R-13 | -83,145.09 | 37,408.39 | | | |
| R-14 | -83,136.75 | 37,408.07 | | | |
| R-15 | -83,127.53 | 37,407.94 | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |


平面直角座標系：第IX系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度 令和5年度

急傾斜地の位置 箇所番号 II-123K2127-3 箇所名 久我原5 所在地 夷隅郡大多喜町久我原、三又



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度 令和5年度

| | | | | | | |
|---------|------|---------------|-----|------|-----|---------------|
| 急傾斜地の位置 | 箇所番号 | II-123K2127-3 | 箇所名 | 久我原5 | 所在地 | 夷隅郡大多喜町久我原、三又 |
|---------|------|---------------|-----|------|-----|---------------|

| 危害のおそれのある土地の座標 | | | | | |
|----------------|------------|-----------|------|------|------|
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
| Y-1 | -83,274.02 | 37,329.34 | | | |
| Y-2 | -83,271.24 | 37,344.87 | | | |
| Y-3 | -83,269.87 | 37,352.56 | | | |
| Y-4 | -83,267.47 | 37,366.65 | | | |
| Y-5 | -83,266.38 | 37,375.52 | | | |
| Y-6 | -83,265.71 | 37,383.96 | | | |
| Y-7 | -83,226.14 | 37,380.00 | | | |
| Y-8 | -83,224.17 | 37,369.27 | | | |
| Y-9 | -83,223.60 | 37,368.35 | | | |
| Y-10 | -83,221.17 | 37,366.74 | | | |
| Y-11 | -83,219.95 | 37,361.16 | | | |
| Y-12 | -83,219.06 | 37,357.13 | | | |
| Y-13 | -83,216.12 | 37,343.67 | | | |
| Y-14 | -83,215.68 | 37,341.68 | | | |
| Y-15 | -83,214.07 | 37,333.88 | | | |
| Y-16 | -83,224.39 | 37,331.60 | | | |
| Y-17 | -83,221.41 | 37,328.39 | | | |
| Y-18 | -83,222.62 | 37,319.68 | | | |
| Y-19 | -83,232.26 | 37,322.34 | | | |
| Y-20 | -83,238.02 | 37,323.94 | | | |
| Y-21 | -83,247.26 | 37,326.58 | | | |
| Y-22 | -83,250.84 | 37,327.34 | | | |
| Y-23 | -83,257.02 | 37,327.16 | | | |
| Y-24 | -83,266.33 | 37,327.80 | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

| 著しい危害のおそれのある土地の座標 | | | | | |
|-------------------|------------|-----------|------|------|------|
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
| R-1 | -83,274.02 | 37,329.34 | | | |
| R-2 | -83,271.24 | 37,344.87 | | | |
| R-3 | -83,269.87 | 37,352.56 | | | |
| R-4 | -83,269.65 | 37,353.87 | | | |
| R-5 | -83,248.59 | 37,364.09 | | | |
| R-6 | -83,220.81 | 37,365.08 | | | |
| R-7 | -83,219.95 | 37,361.16 | | | |
| R-8 | -83,219.06 | 37,357.13 | | | |
| R-9 | -83,217.39 | 37,349.47 | | | |
| R-10 | -83,230.68 | 37,345.16 | | | |
| R-11 | -83,236.42 | 37,333.58 | | | |
| R-12 | -83,237.43 | 37,323.77 | | | |
| R-13 | -83,238.02 | 37,323.94 | | | |
| R-14 | -83,247.26 | 37,326.58 | | | |
| R-15 | -83,250.84 | 37,327.34 | | | |
| R-16 | -83,257.02 | 37,327.16 | | | |
| R-17 | -83,266.33 | 37,327.80 | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

平面直角座標系: 第IX系(測地成果2011)