


# 急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度	令和5年度
------	-------

急傾斜地の位置	箇所番号	II-132K2174	箇所名	成川4	所在地	鴨川市成川、松尾寺
---------	------	-------------	-----	-----	-----	-----------



# 急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	令和5年度					
急傾斜地の位置	箇所番号	II-132K2174	箇所名	成川4	所在地	鴨川市成川、松尾寺

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-95604.59	17142.69	Y30	-95539.61	17207.47	R1	-95598.26	17137.54			
Y2	-95590.68	17143.78	Y31	-95547.18	17207.15	R2	-95585.78	17136.97			
Y3	-95577.51	17142.43	Y32	-95549.60	17207.05	R3	-95574.93	17135.51			
Y4	-95566.08	17146.40	Y33	-95576.20	17205.93	R4	-95565.64	17138.97			
Y5	-95566.06	17146.02	Y34	-95587.65	17205.45	R5	-95565.38	17134.62			
Y6	-95565.38	17134.62				R6	-95565.34	17133.88			
Y7	-95565.09	17129.73				R7	-95573.74	17132.30			
Y8	-95564.83	17125.30				R8	-95581.36	17130.81			
Y9	-95564.50	17119.75				R9	-95591.69	17132.20			
Y10	-95569.07	17119.74				R10	-95593.58	17133.73			
Y11	-95572.65	17118.69									
Y12	-95579.45	17122.25				R11	-95584.86	17205.57			
Y13	-95580.74	17123.30				R12	-95581.83	17209.51			
Y14	-95587.21	17128.55				R13	-95573.88	17230.58			
Y15	-95593.58	17133.73				R14	-95560.59	17231.70			
Y16	-95599.59	17138.62				R15	-95555.17	17226.50			
						R16	-95549.98	17221.52			
Y17	-95608.17	17204.59				R17	-95550.46	17216.67			
Y18	-95608.26	17209.71				R18	-95553.39	17209.30			
Y19	-95595.93	17243.68				R19	-95557.91	17206.70			
Y20	-95569.60	17240.35				R20	-95576.20	17205.93			
Y21	-95568.69	17239.47									
Y22	-95555.17	17226.50									
Y23	-95544.79	17216.53									
Y24	-95540.12	17212.06									
Y25	-95537.57	17209.61									
Y26	-95537.12	17209.18									
Y27	-95536.10	17209.18									
Y28	-95535.85	17207.99									
Y29	-95537.06	17208.71									

平面直角座標系：第Ⅸ区系(測地成果2011)