



急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度	令和5年度
------	-------

急傾斜地の位置	箇所番号	II-132K2275	箇所名	大幡5	所在地	鴨川市大幡
---------	------	-------------	-----	-----	-----	-------



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和5年度

急傾斜地の位置 箇所番号 *II-132K2275* 箇所名 *大幡5* 所在地 *鴨川市大幡*

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-94600.82	14613.84	Y31	-94565.38	14620.01	R1	-94562.58	14620.50			
Y2	-94595.69	14637.15				R2	-94557.01	14638.41			
Y3	-94578.17	14654.60				R3	-94539.30	14651.96			
Y4	-94584.10	14669.73				R4	-94544.65	14668.60			
Y5	-94588.12	14702.61				R5	-94549.40	14693.51			
Y6	-94563.89	14714.67				R6	-94527.20	14704.81			
Y7	-94558.06	14728.99				R7	-94519.45	14723.37			
Y8	-94568.87	14737.56				R8	-94530.25	14739.57			
Y9	-94571.81	14749.12				R9	-94533.75	14755.82			
Y10	-94554.36	14752.19				R10	-94522.57	14757.79			
Y11	-94522.57	14757.79				R11	-94484.80	14764.43			
Y12	-94478.66	14765.51				R12	-94482.16	14742.07			
Y13	-94474.24	14766.29				R13	-94476.04	14717.04			
Y14	-94470.81	14756.97				R14	-94488.98	14694.54			
Y15	-94467.11	14741.57				R15	-94495.22	14680.76			
Y16	-94465.90	14729.48				R16	-94497.42	14667.24			
Y17	-94463.42	14720.26				R17	-94505.73	14649.67			
Y18	-94461.41	14714.88				R18	-94507.54	14640.01			
Y19	-94460.57	14712.73				R19	-94514.26	14628.90			
Y20	-94471.76	14689.92				R20	-94551.56	14622.41			
Y21	-94477.67	14676.63									
Y22	-94480.02	14666.75									
Y23	-94487.99	14652.24									
Y24	-94490.16	14648.56									
Y25	-94495.20	14637.72									
Y26	-94496.31	14633.90									
Y27	-94497.98	14631.73									
Y28	-94501.78	14631.07									
Y29	-94507.83	14630.02									
Y30	-94551.56	14622.41									

平面直角座標系: 第Ⅸ系(測地成果2011)