



急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度	令和5年度
------	-------

急傾斜地の位置	箇所番号	II-132K2400	箇所名	平塚12	所在地	鴨川市平塚
---------	------	-------------	-----	------	-----	-------



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	令和5年度
------	-------

急傾斜地の位置	箇所番号	II-132K2400	箇所名	平塚12	所在地	鴨川市平塚
---------	------	-------------	-----	------	-----	-------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-96716.46	11373.26	Y30	-96536.29	11425.73	R1	-96714.20	11368.54			
Y2	-96716.30	11372.31	Y31	-96529.22	11424.34	R2	-96709.49	11368.43			
Y3	-96715.89	11372.08	Y32	-96522.35	11423.00	R3	-96708.02	11381.95			
Y4	-96715.89	11372.08	Y33	-96512.86	11421.13	R4	-96703.93	11379.54			
Y5	-96715.17	11370.57				R5	-96707.61	11367.36			
Y6	-96712.15	11364.23				R6	-96712.15	11364.23			
Y7	-96709.31	11358.27									
Y8	-96706.64	11352.66				R7	-96517.66	11422.08			
Y9	-96705.01	11349.25				R8	-96516.32	11415.31			
Y10	-96696.58	11361.07				R9	-96519.67	11402.35			
Y11	-96689.81	11371.20				R10	-96527.75	11390.52			
Y12	-96693.64	11373.46				R11	-96531.89	11392.69			
Y13	-96698.42	11376.28				R12	-96526.04	11404.76			
Y14	-96703.93	11379.54				R13	-96522.96	11416.81			
Y15	-96708.84	11382.43				R14	-96522.35	11423.00			
Y16	-96712.54	11384.62									
Y17	-96716.18	11372.69									
Y18	-96512.54	11421.07									
Y19	-96509.96	11413.86									
Y20	-96513.57	11400.04									
Y21	-96523.03	11388.05									
Y22	-96523.37	11388.23									
Y23	-96531.89	11392.69									
Y24	-96538.98	11396.40									
Y25	-96542.66	11398.32									
Y26	-96547.85	11401.03									
Y27	-96541.63	11410.66									
Y28	-96539.22	11420.50									
Y29	-96539.03	11426.27									

平面直角座標系: 第Ⅸ系(測地成果2011)