


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

| | |
|------|-------|
| 調査年度 | 令和5年度 |
|------|-------|

| | | | | | | |
|---------|------|-------------|-----|------|-----|-------|
| 急傾斜地の位置 | 箇所番号 | II-132K2412 | 箇所名 | 平塚22 | 所在地 | 鴨川市平塚 |
|---------|------|-------------|-----|------|-----|-------|



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和5年度

急傾斜地の位置 箇所番号 II-132K2412 箇所名 平塚22 所在地 鴨川市平塚

| 危害のおそれのある区域の座標(土砂災害警戒区域) | | | | | | 著しい危害のおそれのある区域の座標(土砂災害特別警戒区域) | | | | | |
|--------------------------|-----------|---------|------|-----------|---------|-------------------------------|-----------|---------|------|------|------|
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
| Y1 | -95699.92 | 9749.09 | Y30 | -95842.83 | 9758.36 | R1 | -95782.32 | 9764.46 | | | |
| Y2 | -95695.26 | 9750.66 | Y31 | -95850.88 | 9762.84 | R2 | -95792.04 | 9759.46 | | | |
| Y3 | -95695.29 | 9751.38 | Y32 | -95851.57 | 9763.22 | R3 | -95781.17 | 9740.96 | | | |
| Y4 | -95716.43 | 9770.53 | Y33 | -95860.63 | 9745.67 | R4 | -95773.44 | 9719.44 | | | |
| Y5 | -95719.37 | 9771.86 | Y34 | -95861.33 | 9746.93 | R5 | -95763.04 | 9723.68 | | | |
| Y6 | -95723.36 | 9773.28 | Y35 | -95859.05 | 9741.94 | R6 | -95748.07 | 9729.77 | | | |
| Y7 | -95728.61 | 9775.03 | Y36 | -95857.17 | 9737.83 | R7 | -95721.09 | 9741.94 | | | |
| Y8 | -95736.54 | 9778.04 | Y37 | -95855.32 | 9733.77 | R8 | -95710.72 | 9745.44 | | | |
| Y9 | -95742.78 | 9780.72 | Y38 | -95852.78 | 9730.43 | R9 | -95733.30 | 9765.77 | | | |
| Y10 | -95744.75 | 9781.70 | Y39 | -95848.89 | 9727.10 | R10 | -95760.88 | 9777.88 | | | |
| Y11 | -95746.55 | 9782.74 | Y40 | -95846.90 | 9725.71 | R11 | -95764.20 | 9775.58 | | | |
| Y12 | -95749.52 | 9784.55 | Y41 | -95831.16 | 9714.66 | R12 | -95774.32 | 9768.58 | | | |
| Y13 | -95755.35 | 9781.71 | Y42 | -95820.71 | 9707.33 | R13 | -95847.59 | 9738.66 | | | |
| Y14 | -95756.14 | 9781.16 | Y43 | -95824.70 | 9726.34 | R14 | -95854.96 | 9733.29 | | | |
| Y15 | -95764.20 | 9775.58 | | | | R15 | -95852.78 | 9730.43 | | | |
| Y16 | -95774.32 | 9768.58 | | | | R16 | -95848.89 | 9727.10 | | | |
| Y17 | -95782.32 | 9764.46 | | | | | | | | | |
| Y18 | -95822.36 | 9743.88 | | | | R17 | -95846.90 | 9725.71 | | | |
| Y19 | -95826.79 | 9741.60 | | | | R18 | -95839.45 | 9720.48 | | | |
| Y20 | -95816.50 | 9725.47 | | | | R19 | -95836.69 | 9732.79 | | | |
| Y21 | -95809.34 | 9704.82 | | | | R20 | -95828.94 | 9750.47 | | | |
| Y22 | -95806.55 | 9705.96 | | | | R21 | -95834.81 | 9753.85 | | | |
| Y23 | -95763.04 | 9723.68 | | | | R22 | -95836.39 | 9754.77 | | | |
| Y24 | -95748.07 | 9729.77 | | | | R23 | -95838.37 | 9755.87 | | | |
| Y25 | -95721.09 | 9741.94 | | | | | | | | | |
| Y26 | -95704.18 | 9747.65 | | | | | | | | | |
| | | | | | | | | | | | |
| Y27 | -95819.21 | 9744.86 | | | | | | | | | |
| Y28 | -95834.81 | 9753.85 | | | | | | | | | |
| Y29 | -95836.39 | 9754.77 | | | | | | | | | |

平面直角座標系: 第Ⅸ系(測地成果2011)