


# 急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度 平成28年度

急傾斜地の位置	箇所番号	II-1520	箇所名	小泉1	所在地	成田市小泉1
---------	------	---------	-----	-----	-----	--------



## 急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度

平成28年度

急傾斜地の位置			箇所番号			箇所名			所在地		
			II-1520			小泉1			成田市小泉1		
危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-20392.47	48188.75	Y-31	-20390.92	48164.23	R-1	-20391.70	48176.57			
Y-2	-20368.99	48186.07	Y-32	-20391.27	48169.69	R-2	-20368.70	48172.38			
Y-3	-20353.18	48176.53	Y-33	-20391.29	48170.03	R-3	-20351.90	48166.50			
Y-4	-20341.32	48192.59				R-4	-20337.83	48175.30			
Y-5	-20325.74	48183.98				R-5	-20323.50	48178.23			
Y-6	-20318.10	48210.53				R-6	-20311.12	48198.39			
Y-7	-20301.61	48219.87				R-7	-20293.97	48207.92			
Y-8	-20284.61	48225.28				R-8	-20279.64	48217.27			
Y-9	-20273.15	48255.89				R-9	-20265.70	48240.79			
Y-10	-20253.73	48260.86				R-10	-20244.60	48243.39			
Y-11	-20218.97	48247.96				R-11	-20217.69	48240.50			
Y-12	-20202.56	48245.07				R-12	-20203.11	48239.40			
Y-13	-20203.11	48239.46				R-13	-20203.47	48234.67			
Y-14	-20203.47	48234.67				R-14	-20203.49	48234.42			
Y-15	-20203.92	48228.84				R-15	-20216.32	48232.56			
Y-16	-20204.31	48218.85				R-16	-20234.96	48224.31			
Y-17	-20213.90	48216.60				R-17	-20257.41	48223.98			
Y-18	-20229.56	48208.57				R-18	-20274.03	48208.25			
Y-19	-20248.77	48209.74				R-19	-20285.63	48194.89			
Y-20	-20265.34	48194.26				R-20	-20303.37	48184.90			
Y-21	-20276.92	48181.28				R-21	-20320.81	48172.51			
Y-22	-20295.23	48170.73				R-22	-20334.39	48156.40			
Y-23	-20311.92	48157.87				R-23	-20351.63	48154.75			
Y-24	-20328.49	48141.06				R-24	-20369.66	48156.54			
Y-25	-20354.30	48137.75				R-25	-20390.90	48161.93			
Y-26	-20372.55	48139.81				R-26	-20390.92	48164.23			
Y-27	-20390.92	48143.41				R-27	-20391.27	48169.69			
Y-28	-20390.92	48151.81				R-28	-20391.29	48170.03			
Y-29	-20390.80	48152.60									
Y-30	-20390.81	48153.40									