

急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

平成30年度

急傾斜地の位置

箇所番号



II-1585

箇所名

根古名2

所在地

千葉県富里市根古名宮前



scale:1/1000

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	平成30年度
------	--------

急傾斜地の位置		箇所番号	II-1585	箇所名	根古名2	所在地	千葉県富里市根古名宮前				
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-28760.432	47628.341	R-1	-28764.655	47636.143						
Y-2	-28765.022	47621.595	R-2	-28770.942	47633.996						
Y-3	-28765.022	47621.595	R-3	-28770.942	47633.996						
Y-4	-28770.619	47617.584	R-4	-28776.905	47630.225						
Y-5	-28789.803	47607.826	R-5	-28796.225	47621.279						
Y-6	-28804.977	47599.881	R-6	-28810.394	47611.093						
Y-7	-28818.141	47591.667	R-7	-28823.877	47603.514						