

16. 量水器設置状況

(単位：個)

口径 月	13mm	20mm	25mm	40mm	50mm	75mm	100mm	150mm	200mm	250mm 以上	計
平成30年度	353,663	1,018,662	26,526	6,309	1,980	918	206	76	16	3	1,408,359
前年度増減	7,467	17,477	▲ 38	60	36	▲ 2	▲ 3	0	0	▲ 1	24,996
対前月 増減											
4月	2,387	2,349	17	20	7	2	1	1	0	▲ 1	4,783
5	349	1,298	17	11	26	68	1	1	0	0	1,771
6	387	1,479	▲ 3	8	54	243	14	1	0	0	2,183
7	203	1,230	14	▲ 9	▲ 12	▲ 6	0	0	0	0	1,420
8	69	1,372	▲ 9	3	▲ 17	▲ 90	▲ 8	0	0	0	1,320
9	342	1,258	▲ 25	▲ 5	▲ 34	▲ 215	▲ 6	▲ 2	0	0	1,313
10	▲ 332	1,263	▲ 3	10	3	▲ 3	0	0	0	0	938
11	132	998	▲ 8	7	1	▲ 3	▲ 2	1	0	0	1,126
12	▲ 116	1,008	▲ 20	4	4	1	0	▲ 1	0	0	880
1	▲ 77	754	▲ 3	9	▲ 3	1	▲ 1	0	0	0	680
2	158	1,462	8	6	0	2	▲ 2	0	0	0	1,634
3	3,965	3,006	▲ 23	▲ 4	7	▲ 2	0	▲ 1	0	0	6,948

(注) 取付停止中の量水器をのぞく。

17. 量水器修繕状況 (請負)

(単位：個)

口径 月	13mm	20mm	25mm	40mm	50mm	75mm	100mm	150mm	200mm	250mm	300mm	500mm	計
4月	5,000	11,400	500	0	0	0	0	0	0	0	0	0	16,900
5	5,000	11,000	400	0	0	0	0	0	0	0	0	0	16,400
6	1,700	6,800	400	0	0	0	0	0	0	0	0	0	8,900
7	6,000	13,000	400	200	50	36	0	0	0	0	0	0	19,686
8	7,000	13,000	500	200	40	30	13	0	1	0	0	0	20,784
9	4,000	13,000	450	200	40	20	0	0	0	0	0	0	17,710
10	4,000	13,000	350	100	51	20	13	9	0	0	0	0	17,543
11	3,500	8,000	350	100	40	20	0	0	0	0	0	0	12,010
12	3,500	5,000	250	100	40	34	7	0	0	0	0	0	8,931
1	3,800	3,000	250	100	40	20	0	0	0	0	0	0	7,210
2	2,000	3,000	250	90	40	20	7	8	0	0	0	0	5,415
3	1,100	2,700	0	0	19	20	0	0	0	0	0	0	3,839
合計	46,600	102,900	4,100	1,090	360	220	40	17	1	0	0	0	155,328